



ITEM NO.	QTY.	DESCRIPTION
33	1	gasket
42	1	gasket
43	1	seat
44	1	o-ring
45	1	o-ring
49	1	pilot armature with spring
54	1	o-ring

**PROPRIETARY AND CONFIDENTIAL**  
 THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF BREAKER SERVICE INC. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF BREAKER SERVICE INC. IS PROHIBITED. COPYRIGHT 2004

**BREAKER SERVICE INC**  
 800-826-5250 office 888-267-7690 fax

Pilot valve repair kit for Parker Hannifin control valve used on Allis Chalmers / Siemens type BZO breakers with type PN-70-T2 & PN-90-T2 mechanisms

REV: **A** DWG. NO. **38125AMK** REV: **0**  
 SCALE: 1:2 Date: 06-09-2004 SHEET 1 OF 1